


PT Male Head Plug



Brass Mark : FAT
Soft Steel Mark : GAT
Stainless Steel Mark : GCA

Item No	Description	Thread		Dimension (mm)				
		T (PT)	T1	L	L1	L2	L3	H
I01	1/8	1/8-28		16.5				12
I02	1/4	1/4-19		19				14
I04	3/8	3/8-19		20				17
I05	1/2	1/2-14		23.5				21
I07	3/4	3/4-14		29				27
I08	1	1-11		33				33.3
I09	1 1/4	1 1/4-11		36				41
I0A	1 1/2	1 1/2-11		39				50
I0D	2	2-11		47				65