


Welding Branch Tee Connector (High Pressure)



Soft Steel Mark : GHE

Item No	Description	Thread	LBS					
			2000			3000		
	Welding	T	L	L1	D	L	L1	D
I22	1/4 x 1/4		48	24	26	56	28	33.5
I44	3/8 x 3/8		56	28	33.5	66	33	38.5
I55	1/2 x 1/2		66	33	38.5	75	37.5	46
I77	3/4 x 3/4		75	37.5	46	88	44	56
I88	1 x 1		88	44	56	103	51.5	62
I99	1 1/4 x 1 1/4		103	51.5	62	120	60	75.5
IAA	1 1/2 x 1 1/2		120	60	75.5	126	63	84.5
IDD	2 x 2		126	63	84.5	170	85	110